

FIGURE 1





FIGURE 2

7/06/07

SERVICE NUMBER ITEM MASTER INQUIRY

07:13:34

Item Number..... 7027275

Item Description.... NLA - RING, SENSOR

Vendor Number.....

Vendor Name.....

Vendor Item Number..

Item Text..... 0920113

11/27/2006 - PER THE VENDOR THIS SENSOR RING IS
NOT A FIELD SERVICEABLE ITEM, IT REQUIRES A
SPECIAL TOOL TO INSTALL WHICH IS NOT AVAILABLE FOR
PURCHASE.

Press Enter to Continue